# **IEEE POWER & ENERGY SOCIETY / SUBSTATIONS COMMITTEE**



2011 - 2012 Officers

CHAIR John Randolph Pacific Gas & Electric 1919 Webster St. (Room 406) Oakland, CA 94612 Phone: 510-874-2680 Fax: 510-874-2314 Email: jdr9@pge.com

**VICE-CHAIR** Mike Dood Schweitzer Engineering Laboratories 15350 W. National Avenue, Suite 205 New Berlin, WI 53151-5119 Phone: (509) 336-7133 Fax: (262) 789-8470 Email: mike\_dood@selinc.com

SECRETARY

Markus Etter ABB Inc. Power Products Division3 Independence Way, Suite 206 Princeton, NJ 08540 Phone: (732) 932-6250 Fax: (732) 932-6272 Email: <u>markus.etter@us.abb.com</u>

C3 Working Group Meeting Notes 2012 JTCM Garden Grove, CA

Monday, 1/9/12 11AM

#### C3: IEEE C37.1 Standard for Supervisory Control And Data Acquisition (SCADA) and **Automation Systems** Chair: C. Preuss Vice Chair: Secretary: E. William **Output: Standard**

Name	Company	Web	M/G
Edward William Jr	SPX Transformer	No	М
John Tengdin	OPUS Consulting Group	No	СМ
Sam Sciacca	SCS Global	No	СМ
Herb Falk	SISCO	No	G
Craig Preuss	Black&Veatch	No	М
Jim Bougie	ABB	No	G
Mason Clark	DAQ	No	СМ
Eric Thibodeau	Cooper Power Systems	No	G
Bogdan Popsecu	GE DE	No	G
Mark Simon	ComEd	No	G
Tim Tibbals	SEL	No	G
Chris Huntley	SEL	No	G
Marc Lacroix	Hydro Quebec	No	СМ
Yoshi Serizawa	CRIEPI	No	G
Dan Nordell	Xcel Energy	No	G

#### C0 Meeting Notes

Name	Company	Web	M/G	
Dan Friedman	Amdocs Canadian Managed Services	Yes	М	
David Haynes	Alclara	Yes	G	
Marcus Steel	Powerlink	Yes	G	
Wai Tsang	TecSec	Yes	G	
Greg Luri	GE Energy	Yes	СМ	
Adi Mulawarman	Xcel Energy	No	М	
M: Member G: Guest CM: Corresponding member				

#### Agenda

Call to Order

Presentations

Old Business

**New Business** 

Next Meeting

Adjourned

#### **Old Business**

- 1) PAR submitted
- 2) New items to address in standard
- 3) Add formal definitions
  - a) Substation integration
  - b) Substation automation
  - c) IED
- 4) Split into standard for master station (outside SUBS scope) and standard for substations
- 5) Keep tables or not?
- 6) Tables were really start of data requirements between interfaces that are similar to the interfaces of SGIP
- 7) Align with SGIP
- 8) Consider reorganizing into "testable requirements" versus design approach could be C37.1.1 or separate, new standard?
  - a) What testable requirements are missing?
  - b) Use as informative standard that point to 1613, 1615, 1711, 1815, etc.

#### IEEE PES Substations Committee

### C0 Meeting Notes

- 9) Operational versus non-operational data
- 10) Availability
  - a) Discuss availability and how it is calculated
  - b) Discuss difference between hardware and software communications availability

DRAFT

- 11) Add point list as important design tools
- 12) Discuss synchrophasors
- 13) Action items
  - a) Update NISTR 7628 diagram
  - b) Split C37.1 into two documents
    - i) One standards based testable requirements
    - ii) Recommended practice how to do integration and automation

### New Business

- 1) PAR approved Sept-10-2011
- 2) Title is now "Standard for Supervisory Control And Data Acquisition (SCADA) and Automation Systems"
- 3) NISTR 7628 diagram update
- 4) C37.1 split up results
- 5) Alignment with 61850-90-2
- 6) Add better reference to serial port characteristic requirements
  - a) We have normative reference to ANSI X3.1, Information Systems—Data Transmission— Synchronous Signaling Rates.
  - b) No specific reference in the text, but specifies levels up to 2048 bps
  - c) EIA-232-F has an upper limit of "20,000 bits per second" but no specification of levels, ie 2400, 4800, 9600, 19.2k, etc
  - d) Per TIA-EIA-562 "Electrical Characteristics for an Unbalanced Digital Interface" goes up to a maximum of 64 kbp/s, but no specification of levels
  - e) TIA 574 actually specifies a DB9 connector for asynchronous ports for speeds supported by TIA 562
  - f) TIA 562 specified maximum of 64 kbps
- 7) More on alarm management (Bill Hollifield in ISA)
  - a) ISA SP-18 Alarm Management committee
  - b) ISA SP101 HMI committee
  - c) The Alarm Management Handbook, 2nd Edition, © PAS 2009
  - d) The High Performance HMI Handbook, © PAS 2008
  - e) The ISA book: Alarm Management: A Comprehensive Guide, © ISA 2011
  - f) The Electric Power Research Institute (EPRI) guideline on Alarm Management, released in 2008.
- 8) How should IEDs handle multiple masters and specifically controls (different form of redundancy both pri/bu always active)?
- 9) Logging of high speed data and careful use of OPC (DA versus "newer OPC stuff")
- 10) USB ruggedness
- 11) Colors used for graphics on screens
- 12) Does C37.1 handle RTD and thermocouple performance requirements?
- 13) Difference between a substation gateway and server?

C0 Meeting Notes

# Future meetings

- 1) May 20-24, 2012: PES Substations Annual Meeting in Raleigh, NC
- 2) September 10-12, 2012: PSRC September meeting in Portland, OR
- 3) January 2013: PES JTCM has not been announced yet

# Notes

- 1) Most discussion was centered on NISTR 7628 "spaghetti diagram" and the contribution made by Adi Mulawarman via email.
- 2) The decision was to look into IEC 61850 and IEC 61850-90-2 report for help with generic interface definitions
  - a) Marc Larcroix, John Tengdin, Jim Bougie, Mason Clark, and Bogdan Popsecu are interested in supporting this effort.
- 3) Discussion took place regarding a split of C37.1 into a recommended practice and standard (1.1).
  - a) The chair indicated that this exercise was interesting in that it was more difficult to do than anticipated
  - b) Much of what was there was in line with 1613
  - c) A request was made to circulate draft 1.1 showing "the split"
- 4) Little else was accomplished under new business after alignment with 61850-90-2 listed above, but the items were quickly reviewed by the chair