IEEE POWER & ENERGY SOCIETY / SUBSTATIONS COMMITTEE



2011 – 2012 Officers

CHAIR
John Randolph
Pacific Gas & Electric
1919 Webster St. (Room 309)
Oakland, CA 94612
Phone: 510-874-2680
Fax: 510-874-2507

Email: jdr9@pge.com

Mike Dood Schweitzer Engineering Laboratories 15350 W. National Avenue - Suite 205 New Berlin, WI 53151-5119 Phone: 262-789-8268 Fax: 262-789-8470

Email: mike dood@selinc.com

Mark Etter
ABB Inc.
3 Independence Way, Suite 206
Princeton, NJ 08540
Phone: (732) 932-6250
Fax: (732) 932-6272
Email: markus.etter@us.abb.com

SECRETARY

Working Group E3, "Guide For Substation Fire Protection"

VICE CHAIR

Meeting Agenda, Chicago, IL

Wednesday, May 18, 2011

1.	 Welcome, introductions and attendance. Per section 9.5 of the WG O&M manual, a quorum requires half the working group members to be in attendance 	Don Delcourt
2.	Slides from IEEE regarding patents in standards and inappropriate topics for working group meetings.	Don Delcourt
3	Review notes from last meeting in Nashville	Don Delcourt
4.	Review PAR and project status	Don Delcourt
5.	Review ballot comments and recommendations by subgroups. Technical comments Editorial comments if time permits Assignment of specific rewrites to individuals Vote on response to comments. Per section 9.2 of the WG O&M manual, a majority vote of the quorum is required	All
6.	 Next steps Rewrite of specific sections (due 2 wks after meeting) If no quorum at the meeting, then email vote on WG's response to the comments (1 wk after meeting) Revise document based on WG's response (2 wks) WG vote on approving revised document for submission to Subcommittee chair for recirculation. (1 wk) Recirculation of document (no more than 10 days) 	All
7.	Round table	All
8.	Review action items, next steps and need for Fall meeting	All
9.	Adjourn	

