

Sunday May 22, 2016

	C	D	E Chastain 1	I	CIGRE Chastain 2
7:00 AM					
Continental Breakfast (The Overlook, 6th Floor)					
8:00 AM					
9:00 AM			Tutorial - E2 Guide 980 Substation Oil Containment		
10:00 AM					
Break (The Overlook, 6th Floor)					
10:15 AM			Tutorial - E2 Guide 980 Substation Oil Containment		
12:00 PM					
Lunch Break (on your own)					
1:30 PM					
2:30 PM			Tutorial - E5 Std 1264 Animal Deterrents		Tutorial - CIGRE Air Ins. Subst. Design for Severe Climate Conditions
3:00 PM					
3:30 PM					
Break (The Overlook, 6th Floor)					
3:45 PM			Tutorial E5 - Std 1264 Animal Deterrents		Tutorial - CIGRE SF6 Application & Responsible Use - Challenges & Options
5:15 PM					
5:30 PM					
6:00 PM	New Member Orientation (Chastain F, 6th Floor)				
7:00 PM					
7:30 PM	Welcome Reception Sundial (The Bar, 73rd Floor)				
9:30 PM					

Monday May 23, 2016

		B Chastain F	C Chastain I/J	D Chastain 1	E Chastain G	I Chastain H	K Chastain E
6:30 AM	Technical Tours	Companion Tour					
7:00 AM		B0 Admin Sub Cmte.	Continental Breakfast (The Overlook, 6th Floor)				
7:30 AM							
8:00 AM			A0 – Main Substations Committee (Peachtree Ballroom D, 8th Floor)				
9:30 AM			Break (Peachtree Pre-Function, 8th Floor)				
9:45 AM			A0 – Main Substations Committee (Peachtree Ballroom D, 8th Floor)				
11:00 AM		All About Atlanta - City Tour	C5 - PC37.2 Device Functions and Acronyms	D0 Subcommittee	E0 joint meeting with D0		K0 GIS Subcommittee
12:00 PM			Awards Luncheon (Peachtree Ballroom C, 8th Floor)				
1:00 PM							
1:30 PM							
2:00 PM			C12 - P1815 DNP3	vo	E5 Animal Deterrents	I0 - High- Voltage Power Electronics Subcommittee	K2 GIS/GIL Tutorial
2:30 PM			C14 - P1815.1 DNP3<->61850				
3:00 PM			Break (The Overlook, 6th Floor)				
3:15 PM	Tech Tour #1 - The Southwire Energy Center		C2 - P1613 Environmental Requirements	D5-Direct Stroke Shielding	E5 Animal Deterrents	I0 - High- Voltage Power Electronics Subcommittee	K10 GIS Handbook 2nd Ed
4:00 PM							
4:30 PM							
5:00 PM							
6:30 PM							
		B0 Admin Sub Cmte.					
9:30 PM							

Tuesday May 24, 2016

	Technical Tour	Companion Tour	B - Chastain F	C Chastain I/J	D Chastain G	Cigre Chastain 2	E Chastain 1	I Chastain H	K Chastain E
6:30 AM--									
7:00 AM --			B0 Admin Subcmte	Continental Breakfast (The Overlook, 6th Floor)					
8:00 AM --					E1-Community Acceptance	CIGRE B3.44	E4 - Substation Safety	I5 - Voltage Sourced Converters (SVCs)	K15 Recommend Practices Field Test GIS
9:45 AM--									
10:00 AM--			Break (The Overlook, 6th Floor)						
10:15 AM--				C4 - PC37.237 COMTAG C15 - P2030.100 Implementing IEC 61850	D2 - Cable	CIGRE B3.44 Subs servicing & supervision w/ mobile devices and smart sensing	E4 - Substation Safety	I5 - Voltage Sourced Converters (SVCs)	K15 Recommend Practices Field Test GIS
10:45 AM--									
11:00 AM--		"A Taste of Atlanta: Downtown Southern Food Walking Tour"	Lunch Break (on your own)						
12:00 PM--					D2 - Cable	CIGRE B3.44	E6- Measuring Ground Impedance	I5 - Voltage Sourced Converters (SVCs)	K14 Condition Assessment of GIS/GIL
1:00 PM--									
2:30 PM--			Break (The Overlook, 6th Floor)						
3:00 PM--	Tech Tour #2 - Georgia Power Customer Resource Center			C6 - P1711.1 SCADA (SSPP) C17 - P1711.2 SCADA (SSCP)	D2 - Cable	CIGRE B3.44	E6- Measuring Ground Impedance	I5 - Voltage Sourced Converters (SVCs)	K4 Guide for SF6 Gas Handling
3:15 PM--									
4:00 PM--									
4:30 PM--									
5:00 PM--									
6:00 PM--									K6 GIS Users Group Meeting
8:00 PM--									

Wednesday May 25, 2016

	B Chastain F	C Chastain I/J	D Chastain G	D/E Chastain H	D/E Chastain 1	I Chastain 2	K Chastain E
7:00 AM							
8:00 AM	B0 Admin Sub Cmte.	Continental Breakfast (The Overlook, 6th Floor)					
9:30 AM			D3 - Bus	E7 - Substation Physical Security	D7-Grounding of AC Substations	I9 - Modern Protection System for Static Var Compensators	K13 C37.20.9 MEGIS
10:00 AM	Break (The Overlook, 6th Floor)						
10:15 AM		C8 - P1615 Network Comms in Substations	D3 - Bus	E7 - Substation Physical Security	E6- Task Force on Surface Material Testing	I9 - Modern Protection System for Static Var Compensators	K18 Mobile GIS
12:00 PM	Lunch Break (on your own)						
1:00 PM	E2- Oil Containment (Chastain F)		D9 - AC/DC	D1 - Clearances	E9- Permanent Ground Connections	I9 - Modern Protection System for Static Var Compensators	K18 Mobile GIS K17 Physical Security of GIS K16 NCIT in GIS
2:45 PM							
3:00 PM	Break (The Overlook, 6th Floor)						
3:15 PM	E2- Oil Containment	C3 - PC37.1.1 I/O Requirements for IEDs	D9 - AC/DC	D1 - Clearances	E9- Permanent Ground Connections	I9 - Modern Protection System for Static Var Compensators	K1 GIS Standard
5:00 PM							
6:30 PM	Social Banquet Atlanta History Center (Meet at the Overlook, 6th Floor)						
10:00 PM							

Thursday May 26, 2016

	C Chastain I/J	D Chastain G	E Chastain H	I Chastain E
7:00 AM	Continental Breakfast (The Overlook, 6th Floor)			
8:00 AM	C20 - PC37.1.2 Databases in SAS	D8 - Turnkey	E3- Fire Protection	I4 - Static Var Compensator
9:00 AM	C19 - PC37.249 Security of Data Files			
10:00 AM--	Break (The Overlook, 6th Floor)			
10:15 AM--	PC37.238 - PTP Power Profile	D8 - Turnkey	E3- Fire Protection	I4 - Static Var Compensator
11:00 AM--	C16 - P2030.102.1 IPSEC			
12:00 PM	Lunch Break (on your own)			
1:00 PM	C18 - PC37.248 COMDEV	D8 - Turnkey		I4-TF2
2:00 PM				
3:00 PM	Break (The Overlook, 6th Floor)			
3:15 PM	C0 Subcommittee	D8 - Turnkey		I4-TF2
5:00 PM				